

School	Status	Item	Estimate - shaded cells are very rough estimates	Condition/Issue	Age	Expected Life Span	HVAC / Boilers / Hot Water Tanks / Plumbing	Roof	Doors repairs	Flooring	Security	Electrical	Athletics / Gyms	Office / Playground
			\$4,013,500.00				\$ 1,155,000.00	\$ 1,000,000.00	\$ 205,000.00	\$ 275,000.00	\$ 300,000.00	\$ 360,000.00	\$ 438,500.00	\$ 280,000.00
HS		Boilers		boiler controls replaced 2017	2002	2022-2032								
HS		Brick/Exterior Walls			2002									
HS		Burglar Alarm			2002									
HS	Y	Door Hardware & locks	\$150,000.00	Ongoing maintenance and repair issues. Building key system not consistent - re-key needed					\$ 150,000.00					
HS		Electrical System			2002									
HS		Elevators & Lifts			2002									
HS	Y	Exterior Lighting	\$20,000.00	security lighting for lower fields									\$ 20,000.00	
HS		Exterior Painting												
HS		Fire Alarm			2002									
HS	R	Flooring	\$50,000.00	Library carpets heavily stained, some VCT issues	2002					\$ 50,000.00				
HS	R	Gym Floor	\$30,000.00	flooring has been resurfaced yearly. Wood boards are rippled from moisture and have heaved several times. Metals strips surrounding flooring loose as original installation never done properly. Floor needs full sanding, repainting and refinish with new metal edging (\$18,200 for just floor refinish- not metal edge fix)	2002								\$ 30,000.00	
HS	R	Gym Divider Curtains	\$25,000.00	Original motors and hardware. Fabric was replaced at some point by local sail maker. Curtains are torn and in poor condition. Need immediate replacement									\$ 25,000.00	
HS	Y	Gym Lights	\$56,000.00	Ballast buzz, some have been replaced and still buzz. LED replacement estimated cost	2002								\$ 56,000.00	
HS	Y	Gym Wall pads	\$7,500.00	pads are damaged from balls - ripped in places - needs replacement									\$ 7,500.00	
HS	Y	Hot Water Tanks	\$100,000.00	one heat bundle replaced - system near end of life span	2002	2012-2017	\$ 100,000.00							
HS	R	HVAC System	\$30,000.00	System need balancing	2002		\$ 30,000.00							
HS		Intercom System			2002									
HS		Interior Lighting			2002									
HS		Interior Painting												
HS		Phone System			2002									
HS		Plumbing			2002									
HS		Roof		some persistent leaks - maintenance issue	2002									
HS	R	Tennis Courts	\$300,000.00	Courts in very poor condition, asphalt heaved, net poles heaved. Courts need complete rebuild - cannot be repaired by resurfacing	2002								\$ 300,000.00	
HS		Windows		some fogged windows from gasket leaking, some hardware issues. Windows lack insect screens	2002									
HS		Scoreboards		replace 2 scoreboards and shot clocks (2)	2002									
HS	Y	Security	\$10,000.00	no swipe card system or panic buttons	2012						\$ 10,000.00			

School	Status	Item	Estimate - shaded cells are very rough estimates	Condition/Issue	Age	Expected Life Span	HVAC / Boilers / Hot Water Tanks / Plumbing	Roof	Doors repairs	Flooring	Security	Electrical	Athletics / Gyms	Office / Playground
Gerry	R	Electrical System	\$200,000.00	insufficient electrical capacity										
Gerry	Y	Elevators & Lifts	\$500,000.00	not handicap accessible										
Gerry		Exterior Lighting		little exterior lighting										
Gerry		Exterior Painting		wood trim needs painting and repair - some trim missing										
Gerry		Fire Alarm												
Gerry	R	Flooring	\$200,000.00	worn carpet and flooring materials throughout the building										
Gerry		Hot Water Tanks												
Gerry	R	HVAC System	\$150,000.00	heat control very poor - sytem well past lifespan										
Gerry	Y	Intercom System	\$20,000.00	very old intercom system - only accessible from main offie										
Gerry		Interior Lighting												
Gerry	R	Interior Painting	\$100,000.00	multiple areas of water damage - ceilings need repair										
Gerry		Phone System												
Gerry		Playground												
Gerry	Y	Plumbing	\$200,000.00	original plumbing - hard to get parts		1906								
Gerry	R	Roof	\$750,000.00	Slate roofing materials loose and falling - many roof leaks		1906								
Gerry	Y	Security	\$50,000.00	No panic buttons or security cameras										
Gerry	R	Windows	\$600,000.00	1970's replacement windows have failed springs and fogged over lexan - no insect screens		1970's								
Upper Bell	Y	Bathrooms	\$30,000.00	Metal partitions rusted and need replacement.		1970			\$ 30,000.00					
Upper Bell	R	Boilers	\$175,000.00	Boiler approaching end of life span - has 9 of 26 sections blocked off and leaks regularly		1970	\$ 175,000.00							
Upper Bell		Brick/Exterior Walls		come foundation concrete spalling		1970								
Upper Bell		Burglar Alarm		no burglar alarm										
Upper Bell		Door Hardware & locks		front entry doors have frequent hardware issues										
Upper Bell	Y	Electrical System	\$250,000.00	capacity issues in certain areas of the building due to window ac units		1970						\$ 250,000.00		
Upper Bell		Elevators & Lifts		no elevators or lifts										
Upper Bell		Exterior Lighting		limited exterior lighting										
Upper Bell		Exterior Painting		wood trim needs repainting										
Upper Bell		Fire Alarm		new alarm in 2015		2015								
Upper Bell		Flooring		old carpets replaced with new VCT in 2014-2015										
Upper Bell	Y	Hot Water Tanks	\$50,000.00	pony water heater system has regular issues - well past lifespan		1970	\$ 50,000.00							
Upper Bell	R	HVAC System	\$200,000.00	Temp control system needs complete replacement. Classroom AC units very old and run off non dedicated AC outlets, AC roof top units for office, Library and teacher's room well past lifespan.		1970	\$ 200,000.00							
Upper Bell	R	Intercom System	\$30,000.00	1970 intercom system failing. Only accessible from main office		1970						\$ 30,000.00		

